

Tool Operating Manual

i06060028

458-0899 Latchfree Dipper Link Arm Swivel Lift

SMCS Code: 0374; 0599; 0629; 0632; 1122; 6000; 6001; 6459; 6513; 7000

Electric Rope Shovel 7495 (S/N: ER61-Up) 7495 HD (S/N: ER71-Up) 7495 HF (S/N: ER81-Up)

Table of Contents

Introduction	1
Literature Information	2
Safety Section	2
General Information Section	2
Operation Section	2
Maintenance Section	2
Safety Section	
General Hazard	2
Information	2
Crushing Prevention and Cutting	
Prevention	
Safety Icon Nomenclature	3
Personal Protection/Important	
Information	
Hazard Avoidance	
Additional Contact Information	
General Information Section	
Introduction	
References	
Operation Section	5
Setup	
Inspection and Maintenance Section	
Inspection	
Cleaning	
Storage	
Tool Disposal	6

Introduction

Important Safety Information



Illustration 1

q02139237

Think Safety

Most accidents that involve product operation, maintenance, and repair are caused by failure to observe basic safety rules or precautions. An accident can often be avoided by recognizing potentially hazardous situations before an accident occurs. A person must be alert to potential hazards. This person should also have the necessary training, skills, and tools to perform these functions properly.

Improper operation, lubrication, maintenance, or repair of this product can be dangerous and could result in injury or death.

Do not operate or perform any lubrication, maintenance, or repair on this product until you have read and understood the operation, lubrication, maintenance, and repair information.

Safety precautions and warnings are provided in this manual and on the product. If these hazard warnings are not heeded, bodily injury or death could occur to you or to other persons.

The hazards are identified by the Safety Alert Symbol and followed by a Signal Word such as "DANGER", "WARNING", or "CAUTION". The Safety Alert "WARNING" label is shown below.

A non-exhaustive list of operations that may cause product damage are identified by "NOTICE" labels on the product and in this publication.